



सत्यमेव जयते

Office of the Director of Boilers,
4th Floor, Shram Bhavan, Near Gun House, Rustom Cama Marg, Khanpur, Ahmedabad-380001
Phone : 079- 25505066- 25505067 Fax: 079- 25505061
e-mail :- cisbnsn-lab-ahd@gujarat.gov.in & Web site :- <http://www.boiler.gujarat.gov.in>

No. DOB/TECH/2015/ 18240

Date: - 8 SEP 2015

To,
The Proprietor,
HARSHAD ENGINEERING WORKS,
S - 121 to 124, Vivekanand Estate,
Near Rakhial Cross Road,
Rakhial, Ahmedabad - 380 023.

Sub: Approval of your workshop for manufacturing of **Safety Valves** under inspection of I.B.R -1950.

Ref: 1 Your letter no. nil dtd. 12/06/2015.
2 Letter no. nil dtd. 17/06/2015.
3 Letter no. HEW / IBR / Challan dtd. 08/09/2015.
4 Visit of Deputy Director of Boilers Shri J. I. Patel, Ahmedabad Region on dtd. 08/08/2015 for verification of staff & workshop facilities.
5 Government of Gujarat Notification no. GR - 2007 - 73- IBA - 1099 - 1895 (I) - M - (3) dtd. 31/08/2007.

Sir,


With reference to above you are permitted for **two year** for manufacturing of valves from **80 NB (3") x 100 NB (4") x 150 #, 300 # & ' H ' Table Cast Safety Valves** under inspection of I.B.R.- 1950 subject to the following conditions.

1. Drawings of above items must be got approved before starting manufacturing where ever required.
2. Casting must be obtained or inspected under IBR -1950 from well known / approved foundry.
3. All the material must be offered for inspection along with material test certificates before use wherever applicable.

4. Before starting machining casting must be offered for inspection if applicable.
5. Valves must be offered for stage wise inspection during manufacturing as per instruction of the Inspectorate.
6. All the work should be carried out strictly in accordance with Indian Boilers Regulation-1950 to the satisfaction of the Inspecting Officer and Inspecting Authority.
7. You shall have to carryout manufacturing of above items as per the instruction issued from time to time either by Inspecting Officer or by Inspecting Authority.
8. Welders must be qualified in appropriate material as per requirement of Chapter-I & XIII of Indian Boiler Regulation -1950 before starting the job in same material.
9. Items must be offered for stage wise inspection during manufacturing as per instruction of the Inspectorate wherever applicable
10. You will have to inform this office immediately if there is any change in existing name of the company / existing technical staff of the company.
11. **This permission can be withdrawn at any time without giving notice if the workmanship /quality is found unsatisfactory.**
12. **You are hereby instructed to get it renewed before 60 days from the expiry of this certificate.**

Voucher no. 3150 of Rs. 5,000/- dtd. 08/09/2015 for registration fees is enclosed here with.

Yours Faithfully,



(R.N.Charel)

Director of Boilers,
Gujarat State, Ahmedabad.

Copy to: D.O.B / TECH / 2015 /

dtd :

1. Shri J. I. Patel, Deputy Director of Boilers, Ahmedabad Region for information and necessary action.
2. Shri R. B. Joshi, Assistant Director of Boilers, Ahmedabad - 2 division for information and necessary action.